



EOP 350 Errata

On the EOP350 Development board that comes in the EDK350 Development kit the EOP connector, labeled SV5, has the TX and RX pins incorrectly labeled. This will only effect the serial communication lines present via this header which is unpopulated by default. The header and associated cable will be drop in compatible with the EOP300 for programming only. If serial communication is required the TX and RX pins need to be swapped in your application. This is pin 5 and 6 on the header.

Programmer interface

