

PCN #: S3001-A535_DC_08-PCN-20210429
Change Title: PTM 535 Product Maintenance
Date of publication: April 29, 2021

Products affected / EnOcean ordering codes

- PTM 535 / S3001-A535

Description of change

- PTM 535 firmware has been extended to provide optional support for 1BS telegram format. This feature can be selected using the PTM 535 configuration interface; the default product behaviour remains unchanged.

Milestones

- New version will be introduced within Q2/2021

Reason for change

- Customer requests to support 1BS telegram format as optional feature

Step codes after change

- S3001-A535: PTM 535 **DC**

Customer impact of change and recommended action

- The default product behaviour remains unchanged; no customer action is required
- Customer wishing to configure PTM 535 to use 1BS telegram should consult the user manual (chapter 4) to determine the system requirements (e.g. programmer and needle adapter). EnOcean can provide demonstration configuration scripts if needed, please contact support@enocean.com for additional information.

Reference Documents

- PTM 535 User Manual

PCN revision history

Date of revision	Author	Revision number	Reason
April 29, 2021	Kreitmair	01	Updated PCN